

Figure 1.




Figure 2. Fringe pattern distribution formed by the shear stress sensor optical assembly.




Figure 3. Fabrication sequence.



Page 3 of 3
Appl. No.: 09/838,344
Amendment in Reply to Office Action of April 26, 2004
Replacement Sheet




Figure 4